

L1Topo Status 11 July 2016

•Firmware: no recent changes

- Test of larger readout buffers unfinished (but looks OK)
- ·Version with J/PSI algorithms restored to be tested

Known HW problems

- •Missing TOBs for octant 0 on the C(?) side
 - •Suspicion its at the source, but will check reverting L1Topo FW
- •Occasional 1-2 bit shift in muon inputs => 40 MHz rates
- •Need to check fine timing of muon inputs (CTP pattern)
 - · Also check its really happening at the L1Topo end
- Also retry Muctpi2topo patch adding GTX reset

Other problems

- •Eta/phi shift (0.1?) between muon and calo TOBs
 - Need to check VHDL mapping of all TOB types