

## LVDS Cable Installation


Murrough Landon 8 November 2006

- PPM-CPM/JEM mapping
- (Im)practicalities
- Likely procedure
- Schedule, requirements & critical items



## PPM and CP/JEP Crate Layouts


- PPM crates are organised like the detector: split into barrel or endcap, EM or hadronic, A or C side.
  One crate has all quadrants for part of the detector
- CP/JEP crates are organised for the algorithms by quadrants: one crate has all the detector (A/C, EM/hadronic) for one quadrant
- The interface between these two worlds is 1888 LVDS cables (+ spares)





## Rack Layout

- PPM racks in outlying racks (flanked by receivers)
- CP/JEP racks in the centre (RODs etc not shown)
- Minimum gap: two racks
- Maximum gap: seven racks





# Cable Groupings

- Every PPM crate has cables to all six CP/JEP crates
  - 48 combinations, but for spares just N \* 12 rack-rack
- Bulk of cabling between "core" regions
  - 8 cables [a..h] from each PPM to one CPM
  - 4 cables [a..h] from each PPM to one JEM
- Additional cabling to overlap/fanout regions across quadrant boundaries
  - 2 cables [v,w] from each PPM to two CPMs (one each)
  - 2 cables [v,wx] from each PPM to two JEMs (one each)
    - Some additional fanout for FCAL and high eta endcap
- Phi runs downwards on PPM backplane, but runs upwards on CP/JEP backplane
- PPM to CP outputs are above PPM to JEP outputs



## PPM LVDS Backplane Connections (1)

#### Preprocessor crate 0: EM Barrel +Z (A side)

						•								•					
5	Slot		5	- 6	7	- 8	9	10	11	12	13	14	15	16	17	18	19	20	
Conn			Quadrant 1					Quad	rant 2			Quad	rant 3		Quadrant 4				
₩			E18w	E19w	E1Aw	E1Bw	E28w	E29w	E2Aw	E2Bw	E38w	E39w	E3Aw	E3Bw	E48w	E49w	E4Aw	E4Bw	
A				E19a	E1Aa	E1Ba	E28a	E29a	E2Aa	E2Ba.	E38a.	E39a.	E3Aa		E48a	E49a	E4Aa	E4Ba	
В			E18b	E19b	E1Ab	E1Bb	E28b	E29b	E2Ab	E2Bb	E38b	E39b	E3Ab	ЕЗВЬ	E48b	E49b	E4Ab	E4Bb	
C			E18c	E19c	E1Ac	E1Bc	E28c	E29c	E2Ac	E2Bc	E38c	E39c	E3Ac	E3Bc	E48c	E49c	E4Ac	E4Bc	
D		<b>a</b>	E18d	E19d	E1Ad	E1Bd	E28d	E29d	E2Ad	E2Bd	E38d	E39d	E3Ad	E3Bd	E48d	E49d	E4Ad	E4Bd	
E		8	E18e	E19e	E1Ae	E1Be	E28e	E29e	E2Ae	E2Be	E38e	E39e	E3Ae	E3Be	E48e	E49e	E4Ae	E4Be	
F			E18f	E19f	E1Af	E1Bf	E28f	E29f	E2Af	E2Bf	E38f	E39f	E3Af	E3Bf	E48f	E49f	E4Af	E4Bf	
G			E18g	E19g	E1Ag	E1Bg	E28g	E29g	E2Ag	E2Bg	E38g	E39g	E3Ag	E3Bg	E48g	E49g	E4Ag	E4Bg	
H			E18h	E19h	E1Ah	E1Bh	E28h	E29h	E2Ah	E2Bh	E38h	E39h	E3Ah	E3Bh	E48h	E49h	E4Ah	E4Bh	
Y			E18v	E19v	E1Av	E1Bv	E28v	E29v	E2Av	E2Bv	E38v	E39v	E3Av	ЕЗВу	E48v	E49v	E4Av	E4Bv	
F1																			
F2																			
Y8																			
WX			E18WX	E19wx	EIAWX	E1Bwx	E28wx	E29wx	E2Awx	E2Bwx	E38w×	E39w×	E3Awx	E3Bw×	E48w×	E49wx	E4Awx	E4Bw×	
AB			E18ab	E19ab	E1Aab	E1Bab	E28ab	E29ab	E2Aab	E2Bab	E38ab	E39ab	E3Aab	E3Bab	E48ab	E49ab	E4Aab	E4Bab	
CD		<u> </u>	E18cd	E19cd	E1Acd	E1Bcd	E28cd	E29cd	E2Acd	E2Bcd	E38cd	E39cd	E3Acd	E3Bcd	E48cd	E49cd	E4Acd	E4Bcd	
EF		Щ	E18ef	E19ef	E1Aef	E1Bei	E28ef	E29ef	E2Aef	E2Bef	E38ef	E39ef	E3Aef	E3Bef	E48ef	E49ef	E4Aef	E4Bef	
GH			E18gh	E19gh	E1Agh	E1Bgh	E28gh	E29gh	E2Agh	E2Bgh	E38gh	E39gh	E3Agh	E3Bgh	E48gh	E49gh	E4Agh	E4Bgh	
YJ			E18vj	E19vj	E1Avj	E1Bvj	E28vj	E29vj	E2Avj	Е2Вуј	Е38уј	E39vj	ЕЗАуј –	ЕЗВуј	E48vj	E49vj	Е4Ауј	E4Bvj	
M8				Ţ					Ī										
F3																			
F4																			

CP: 8 bundles of 16, 8 bundles of 4; JEP: 4 bundles of 16, 8 bundles of 4: total 256



## PPM LVDS Backplane Connections (2)

#### Preprocessor crate 4: Hadronic Endcap/FCAL +Z (A side)

S Conn	Slot
⊗ ∢ворш⊧бну	8
F1 F2 Y8 WX AB CD EF GH YJ	JEP

.M\&.

5	6	7	8	9	10	- 11	12	13	14	15	16	17	18	19	20
F/E		Quedrant	1	Q12		uad rant	2	F/H		Quad rant	3	Q34		uad rant	4
	H1Cw	H1Dw	H1Ew		H2 Cw	H2 Dw	H2Ew		H3 Cw	H3Dw	H3Ew		H4Cw	H4Dw	H4Ew
	H1Ca	H1Da	H1Ea		H2 Ca	H2Da	H2Ea		H3 Ca	H3Da	H3Ea		H4Ca	H4Da	H4Ea
	Н1СЬ	H1Db	H1Eb		Н2 СЬ	H2Db	Н2 ЕЬ		НЗСЬ	НЗВЬ	НЗЕЬ		Н4СЬ	H4Db	H4Eb
	H1Cc	H1Dc	H1Ec		H2 Cc	H2Dc	H2Ec		H3 Cc	H3Dc	H3Ec		H4Cc	H4Dc	H4Ec
	H1Cd	H1Dd	H1Ed		H2 Cd	H2Dd	H2 Ed		H3 Cd	H3Dd	H3Ed		H4Cd	H4Dd	H4Ed
	H1Ce	H1De	H1Ee		H2 Ce	H2De	H2Ee		H3 Ce	H3De	H3Ee		H4Ce	H4De	H4Ee
	H1Cf		H1 Ef				H2 Ef				H3Ef		H4Cf		H4Ef
	_	_	H1Eg		-	_	H2Eg		_	_	H3Eg		_	_	H4Eg
			H1Eh				H2Eh				H3Eh				H4Eh
	H1Cv	H1Dv	H1Ev		H2 Cv	H2 Dv	H2Ev		H3 Cv	H3Dv	H3Ev		H4Cv	H4Dv	H4Ev
E1Gf1								H1 Gf1							
E2Gf2								H2 Gf2							
				H1Fv8			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					H3Fv8			
					H2 Cwx					H3Dwx					
			H1 Eab				H2 Eab								H4Eab
								H2 Gah							H4Ecd
								H3 Gah					H4Cef		H4Eef
E4Gah			780"				H2 Egh						~		H4Egh
	H1Cvj	H1Dvj	L		H2 Cvj	H2Dvj	H2Evi		НЗСу	H3DVj	1	4	H4Cvj	H4Dvj	H4Evi
F0.0/0				H2Fw8				110 000				H4Fw8			
E3Gf3								H3 G/3							
E4Gf4								H4 GM							

Bundling not yet completely thought out...

6



#### CPM LVDS Backplane Connections

#### Cluster Processor crate 0 (quadrant 1)

	BP slot	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
Æ	Eta bin		1	2	3	4	5	6	7	8	9	٨	В	С	D	E	
	Cable								Quad	rant 1							
4	1		E21w	E22w	E23w	E24w	E25w	E26w	E27w	E28w	E29w	E2 Aw	E2Bw	E2Cw	E2Dw	E2Ew	
3	2		E11h	E12h	E13h	E14h	E15h	E16h	E17h	E18h	E19h	E1 Ah	E1Bh	E1Ch	E1Dh	E1Eh	
4	3		H21 w	H22w	H23w	H24w	H25w	H26w	H27w	H28w	H29w	H2Aw	H2Bw	H2Cw	H2Dw	H2Ew	
3	4		H11h	H12h	H13h	H14h	H15h	H16h	H17h	H18h	H19h	H1 Ah	H1Bh	H1Ch	H1Dh	H1Eh	
3	5		E11g	E12g	E13g	E14g	E15g	E16g	E17g	E18g	E19g	E1 Ag	E1Bg	E1Cg	E1Dg	E1Eg	
2	6		E11f	E12f	E13f	E14f	E15f	E16f	E17f	E18f	E19f	E1 Af	E1Bf	E1Cf	E1Df	E1Ef	
3	7		H11g	H12g	H13g	H14g	H15g	H16g	H17g	H18g	H19g	H1 Ag	H1Bg	H1 Cg	H1Dg	H1Eg	
2	8		H11f	H12f	H13f	H14f	H15f	H16f	H17f	H18f	H19f	H1 Af	H1Bf	H1Cf	H1Df	H1Ef	
2	9		E11e	E12e	E13e		E15e		E17e	E18e	E19e	E1 Ae	E1Be	E1Ce	E1De	E1Ee	
1	10		E11d	E12d	E13d	E14d	E15d	E16d	E17d	E18d	E19d	E1 Ad	E1Bd	E1Cd	E1Dd	E1Ed	
2	11		H11e	H12e	H13e	H14e	H15e	H16e	H17e	H18e	H19e	H1 Ae		H1Ce	H1De	H1Ee	
1	12		H11d	H12d			H15d	H16d	H17d	H18d	H19d	H1 Ad	H1Bd	H1Cd	H1Dd	H1Ed	
1	13		E11c	E12c	E13c	E14c	E15c	E16c	E17c	E18c	E19c		E1Bc	E1Cc	E1Dc	E1Ec	
0	14		E11b	Е12ь	E13b	E14b	Е15Ь	E16b	Е17ь	Е18Ь	E19b	E1 Ab	E1Bb	E1Cb	E1Db	Е1ЕЬ	
1	15		H11c	H12c	H13c	H14c	H15c	H16c	H17c	H18c	H19c	H1 Ac		H1Cc	H1Dc	H1Ec	
10	16		H11b	H12b	+		Н15Ь	H16b	Н17Ь	Н18Ь	H19b	†		Н1СЬ	H1Db	H1Eb	
0	17		E11a	E12a	E13a		E15a	E16a	E17a	E18a	E19a	E1 Aa	E1Ba	E1Ca	E1Da	E1Ea	
F	18		E41v	E42v	E43v	E44v	E45v	E46v	E47v	E48v	E49v	E4 Av	E4Bv	E4Cv	E4Dv	E4Ev	
0	19		H11a	H12a	H13a	H14a	H15a	H16a	H17a	H18a	H19a	H1 Aa		H1Ca	H1Da	H1Ea	
F	20		H41 v	H42v	H43v	H44v	H45v	H46v	H47v	H48v	H49v	H4 Av	H4Bv	H4Cv	H4Dv	H4Ev	

C endcap C barrel A barrel A endcap

12 bundles of 16, 4 bundles of 8, 16 bundles of 4 (or 3): total 280



## JEM LVDS Backplane Connections

#### Jet/Energy Processor crate 0 (quadrants 1,3)

	BP slot	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
星	Eta bin	Z,0,1	2,3	4,5	6,7	8,9	A,B	C,D	E,F,G	Z,0,1	2,3	4,5	6,7	8,9	A,B	C,D	E,F,G	摆儿
	Cable				Quad	rant 1							Quac	Irant 3				<u> </u>
	1	H21wx	H23wx	H25wx	H27wx	H29wx	H2Bwx	H2Dwx	H2Fw8	H41wx	H43wx	H45wx	H47wx	lH49wx	H4Bwx	lH4Dwx	H4Fw8	
4	2	E21wx	E23wx	E25wx	E27wx	E29wx	E2Bwx	E2Dwx	E2Fw8	E41wx	E43wx	le45wx	E47wx	le49wx	E4Bwx	le40wx	E4Fw8	C:
	3	H20w8	H22wx	H24wx	H26wx	lH28w×	H2Aw×	lH2Cw×	H2Ew×	H40w8	H42wx	lH44w×	H46wx	lH48wx	H4Aw×	<mark>4</mark> H4Cw×	H4Ewx	
	4	E20w8	E22wx	E24wx	E26wx	E28wx	E2Awx	E2Cwx	E2Ewx	E40w8	E42wx	E44wx	E46wx	JE48wx	E4 Awx	<u>JE4Cwx</u>	E4Ewx	
	5	H11gh	H13gh	H15gh	H17gh	H19gh	H1Bgh	H1Dgh	H1Feh	H31gh	H33gh	H35gh	H37gh	H39gh	H3Bgh	H3Dgh	H3Feh	
3	6	E11gh	E13gh	<b>€</b> 15gh	E17gh	E19gh	E1 Bgh	E1Dgh	E1Feh	E31gh	E33gh	E35gh	E37gh	E39gh	E3Bgh	E3Dgh	E3Feh	в
-	7	H10eh	H12gh	H14gh	H16gh	H18gh	H1 Agh	H1Cgh	H1Egh	H30eh	H32gh	H34gh	H36gh	H38gh	H3 Agh	H3Cgh	H3Egh	
	8	E10eh	E12gh	E14gh	E16gh	E18gh	E1 Agh	E1Cgh	E1Egh	E30eh	E32gh	E34gh	E36gh	E38gh	E3Agh	E3Cgh	E3Egh	
	9	H11ef	H13ef	H15ef	H17ef	H19ef	H1Bef	H1Def	H1 Gah	H31ef	H33ef	H35ef	H37ef	H39ef	H3Bef	H3Def	H3Gah	
2	10	E11ef	E13ef	E15ef	E17ef	E19ef	E1Bef	E1Def	E1Gah	E31ef	E33ef	E35ef	E37ef	E39ef	E3Bef	E3Def	E3Gah	Δ
-	11	H1 Zah	H12ef	_		_		_				H34ef		_	H3Aef	H3Cef	H3Eef	
	12	E1Zah	E12ef	E14ef	E16ef	<u>E18ef</u>	E1 Aef	E1Cef	E1Eef	E3Zah	E32ef	<u>E34ef</u>	E36ef	<u>E38ef</u>	E3Aef	E3Cef	E3Eef	
	13	H11cd	H13cd	H15cd	H17cd	H19cd	H1Bcd	H1Dcd	H1Fad	H31cd	H33cd	H35cd	H37cd	H39cd	H3Bcd	<b>l</b> H3Dcd	H3Fad	
1	14	E11cd	E13cd	E15cd	E17cd	E19cd	E1Bcd	E1Dcd	E1Fad	E31cd	E33cd	E35cd	E37cd	[E39cd	E3Bcd	[E3Dod	E3Fad	9
-	15	H10ad	H12cd	H14cd	H16cd	H18cd	H1 Acd	H1Ccd	H1Ecd	H30ad	H32cd	∥H34cd	H36cd	H38cd	H3 Acd	H3Ccd	H3Ecd	1
												E34cd			E3Acd	4	E3Ecd	
	17											H35ab			H3Bab		H3Gf3	
lo			E13ab									E35ab			E3Bab	E3Dab	E3Gf3	8
-	19	H1Zf1	H12ab									H34ab			H3 Aab		H3Eab	_
			E12ab									E34ab			E3Aab		E3Eab	
	21	H41∨j										H25∨j			Н2В∨ј	_	H2F∨j	
lF	22	E41vj										lE25vj						7
	23	H40vj	_	_	_	_	_	_		_	_	lH24∨j	_	_	_	<b>l</b> H2Cvj	-	
	24	E40vj	E42vj	E44vj	E46vj	E48vj	E4Avj	E4Cvj	E4Evj	E20vj	E22vj	E24vj	E26vj	E28vj	E2Avj	E2Cvj	E2Evj	

Cend Cbar Abar Aend Cend Cbar Abar Aend

16 bundles of 16 (or 12), 32 bundles of 4 (or so): total 384



#### Impracticalities

- LVDS cables are hard to insert correctly, especially on CP/JEP backplane (more per slot in several scattered groups in dark back of crate)
- We need a strain relief, about 20cm behind the backplane, to support the weight of the cables
  - This is removable as it is nearly impossible to insert the cables with the strain relief mechanics in place
  - This is in addition to the retaining mechanism just behind the backplane to keep the cables in place
- The strain relief system needs to have the cables inserted in the right order, bottom up
  - Ie JEP first at the PPM end



# LVDS Strain Relief (for PPM Crate)





## Cable routing

- All cables are 11m longest route 10.7m!
  - Shortest about 5m, so plenty of slack in places
- Rack layout has CP/JEP central and PPM crates at the outsides (A and C sides)
  - Slack cable best stored at the outsides, ie PPM ends
    - Argument for starting bundles at CP/JEP ends
- Route bundles to top crate up sides of the rack
  - For CP/JEP crates chose side closest to source PPM
  - But more space on "power" side than on "water" side
    - May need slightly asymmetrical routing
    - Not clear to me that we actually have enough space!
- Bundles from lower crate can drop straight down
- One set of spares per rack to rack combination



## Suggested Procedure

- Label cables and build rough bundles in 3150
  - Smooth slack in place in USA15 behind racks
- Start at CP/JEP end and do JEP system first
  - CP/JEP strain relief intermingles many sources
  - JEP cables are at bottom of PPM strain relief
- Start with small bundles for "v" overlap, then core (a-h) bundles and finally the "w" overlap
  - Four CPMs or two JEMs at a time
- Fill strain relief with cables in correct order
  - Initially this is further back than its final position
- Insert cables into backplane, move strain relief to correct position and install at back of crate



## Schedule and Requirements

#### Schedule at CP/JEP end:

- First the two JEP crates, followed by CP crates
- Can leave bundles in destination PPM racks until all crates are available

#### Critical path:

- CP/JEP strain relief mechanics (still in design)
- CP/JEP crates (only one installed and CP not JEP)
- Next cabling weeks: 20 November and 4 December
  - Further weeks in 2007: 15 Jan, 29 Jan, 19 Feb, xx Mar(?)

#### Slightly less critical:

- PPM crates and strain relief (two now installed)
- Still thinking about extra tooling to help with installing the cables in the right place