

Online Software M6->M7

Murrough Landon 10 November 2014

- Progress in M6
- •Plans for M7



M6

•PPM

- REM+Calippr FW updated and corresponding SW updated
- ·New readout scheme

· CPM/JEM

- New CPM error counters for CPchip-HitMerger errors
- Trying to understand errors from JEM input timing scan

·ROD

• CMX-CP tested OK

· CMX

- Fleshed out cmxServices: basic configuration
 - •Still not the fine timing setup

·L1Topo

 Also fleshed out topoControl: added ROD configuration, fixed address map, started expanding IGUI panel



Towards M7

•PPM

 Another FW update, bytestream decoders for new ROD formats, start COOL database changes?

•JEM

•Get input timing working again

·ROD

Update rodSim for new PPM formats

· CMX

•Further cmxServices updates, also cmxSim?

·L1Topo

·Plenty of testing: configuration, ROD, compare with simulation



Miscellaneous

- •TDAQ technical run this week
 - ·No access to ROSes this week unless we ask
- · CTP
 - New CTP installation delayed
 - ·No new trigger menu for M7
- Database
 - Changes to our COOL database schema are not yet ready
 - Stick with private sqlite file until after M7