

# More Experience with DAQ -1

**Murrough Landon – 27 October 1999**

- Previous meeting: 0.0.5 CD installed, tried IS, MRS; problems running the noddy DAQ system.
- Now tried version 0.0.6 via AFS to CERN; also tried some corrected scripts for the 0.0.5 version
- (Mostly) successfully worked through the Run Control tutorial - minor problems reported to Bob Jones.
- Initial problems with updated “noddy DAQ system” test. My typo in editing the configuration database eventually spotted by Bob Jones. After that it worked as advertised.
- Noddy run controller built from the example skeleton. Modified with some extra print statements and run via the RC tutorial script.

## Next steps

- Try Integrated GUI; process manager.
- Start giving serious thought to design of ROD DAQ system!